


**FRANKLIN**  
CLEANING TECHNOLOGY



**F3301**

# MegaStar™

## MAXIMUM BRILLIANCE UHS FLOOR FINISH

DATA TECH SHEET

**PRODUCT DESCRIPTION:**

MegaStar™ is an all acrylic, metal crosslinked, self-sealing floor finish developed especially to deliver optimum performance in high-speed maintenance programs. MegaStar's added durability allows for excellent appearance levels even in heavy traffic areas. Use MegaStar™ on all types of resilient surfaces, mineral surfaces and sealed wood. Examples include vinyl, vinyl composition asphalt, linoleum, rubber, terrazzo, quarry tile, unglazed ceramic and sealed wood.

**FEATURES:**

**All Acrylic Formula:**

MegaStar™ goes down clear and stays clear. It will not yellow or discolor when maintained as directed.

**Easy to Apply:**

MegaStar™ goes down effortlessly and levels perfectly each and every coat. MegaStar™ can normally be recoated after 20 minutes.

**Ultra Fast Recoat:**

Less time for the finish to set up, which permits multiple coat applications. Minimizes the adverse effect of temperature and humidity during finish application.

**Safe:**

MegaStar™ passes the James Machine slip resistance test (ASTM D2047-75).

**PRODUCT SPECIFICATIONS:**

|  |                               |
|--|-------------------------------|
| pH .....   | 8.9 ± 0.2                     |
| Appearance .....   | Opaque white emulsion         |
| Freezing Point .....   | About 32°F                    |
| % Solids .....   | 22.5 ± 0.2                    |
| Boiling Point .....  | 212°F                         |
| Flash Point .....  | None                          |
| Coverage .....   | up to 3000 sq. ft. per gallon |
| (may vary due to differences in porosity of the surface and application method used) |                               |

**INGREDIENTS:**

|                                       |            |
|---------------------------------------|------------|
| Water .....                           | 7732-18-5  |
| Styrene acrylic polymer .....         | 25085-34-1 |
| Diethylene glycol methyl ether .....  | 111-77-3   |
| Dipropylene glycol methyl ether ..... | 34590-94-8 |
| Tributoxyethyl phosphate .....        | 78-51-3    |

**ECOLOGICAL INFORMATION:**

- Biodegradable Surfactants
- Contains No Phosphorus
- No Solvents

| DILUTIONS   | HEALTH   | FLAMMABILITY | REACTIVITY |
|-------------|----------|--------------|------------|
| CONCENTRATE | <b>1</b> | <b>0</b>     | <b>0</b>   |
| CONCENTRAR  | <b>1</b> | <b>0</b>     | <b>0</b>   |
| PROPORCIÓN  | <b>1</b> | <b>0</b>     | <b>0</b>   |


| 0       | 1      | 2        | 3       | 4        |
|---------|--------|----------|---------|----------|
| Minimal | Slight | Moderate | Serious | Severe   |
| Mínimo  | Mínimo | Moderar  | Grave   | Drástico |

# MegaStar™ MAXIMUM BRILLIANCE UHS FLOOR FINISH

DIRECTIONS

## USE INFORMATION

Before applying MegaStar™ remove old sealer/finish using an appropriate Franklin stripper following label directions. For use on vinyl composition, rubber, asphalt, quarry, terrazzo and sealed wood floors.



## INITIAL APPLICATION

- REMOVE** old sealer/finish using a Franklin stripper and following label directions.
- APPLY** a thin coat of MegaStar™ using a clean finish mop.
- DRY:** Allow 20-30 minutes drying time.
- APPLY** 3-4 coats for best results. Allow adequate drying time between each coat.

## MAINTENANCE

- DUST MOP** the floor. Remove gum, labels, and other attached soil deposits with a long handled scraper or putty knife.
- DAMP MOP OR AUTOSCRUB** using a quality Franklin cleaner and following the label directions.
- BURNISH** the floor with an appropriate pad and high-speed floor machine (1000-2000+RPM) or spray buff the floor with an electric machine to remove black heel marks, scuffs and scrapes.

Note: To avoid frequent stripping or as the finish begins to show wear, machine clean the floor, rinse and apply two thin coats of MegaStar™.

## FIRST AID:

**If in eyes,** immediately flush with plenty of water. Get medical attention if irritation persists. **If swallowed,** get medical attention. NEVER GIVE ANYTHING BY MOUTH TO AN UNCONSCIOUS PERSON.

## HANDLING AND STORAGE:

**SUGGESTED STORAGE TEMPERATURE:** Store inside at 40-90°F. **SPECIAL HANDLING AND STORAGE:** Handle in accordance with good industrial hygiene and safety practices. These practices include avoiding unnecessary exposure and removal of material from eyes, skin and clothing. Store in a cool and dry ventilated area. Protect from freezing. Thoroughly rinse empty containers. **KEEP OUT OF REACH OF CHILDREN.**

## PERSONAL PROTECTION:

**Respiratory Protection:** Not needed in normal use of this product.

**Ventilation:** Use with adequate ventilation

**Eye Protection:** Safety glasses are optional.

**Protective Gloves:** Safety gloves are optional.

**Other Protective Clothing or Equipment:** Wear clothing as necessary to prevent skin contact.

## TRANSPORTATION INFORMATION:

**U.S. DOT-Proper Shipping Name:** Not restricted by DOT.

**Marine Pollutant:** No

**MSDS RETRIEVAL**  
Read MSDS before using this product  
**800-848-4901**  
[www.franklintechnology.com](http://www.franklintechnology.com)  
**OBTENCIÓN DE HDSM**  
Leer la HDSM antes de utilizar este producto

FOR CHEMICAL EMERGENCY,  
SPILL, LEAK, FIRE, EXPOSURE OR ACCIDENT  
CALL CHEMTREC DAY OR NIGHT  
**800-424-9300**  
PARA EMERGENCIAS QUÍMICA DERRAMES,  
ESCAPES, FUEGO, EXPOSICIÓN O ACCIDENTE  
LLAMAR DE DÍA O DE NOCHE A CHEMTREC

**TECH HOTLINE**  
**800-810-4829**  
**LINEA DE TÉCNICA**

**CLEANING TECHNOLOGIES GROUP®**

a division of CPAC

© **FRANKLIN** Cleaning Technology® 2005 • Great Bend, KS 67530

F3301TDS-1105